

Report

08/16/05

1. Experimental Progress:

- After reinstalling the venturi we run the system just for a couple of hours. I am not sure if the system attained its stability. We had to stop the system because of some required modifications. We are still working on some of the tubing. Hoping that we will be able to run it tomorrow.